

## FIELD INSPECTION

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Matthew Grant
<b>Inspection Date:</b>	Thursday, November 29, 2018	<b>Project Contact:</b>	Brian Clauto
<b>Spread: Franklin County MP 254 St#13444-13416</b>	Spread I	<b>Weather (Wet/Dry/Rain):</b>	Wet

**STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☒ Final Grading & Stabilization

☐ Other:

- |   |   | Yes                                 | No                       | N/A                      |
|---|---|-------------------------------------|--------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |


**Comments:**

- St#13444+00 erosion controls in place and functioning
- St#13431+30-13433+00 erosion controls in place and functioning
- St#13416+00 sediment off site in the uplands and wetlands, upland sediment measurements, 27ft wide and 62 ft long, appx 4 inches deep.

**Recommended Corrective Action:** remove sediment per property owner approval

**Deadline:** Within 24hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.


Inspector Signature:  Date: 12-11-18

## FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, November 29, 2018

- Fig. 1 St#13444+00 erosion controls in place and functioning



- Fig. 2 St#13431 ECD's in place and functioning



- Fig. 3 Area has been stabilized near St#13431-13433



- Fig. 4 Offsite upland area below station 13416+00



## FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, November 29, 2018

Fig. 5 Wetland area below station 13416+00

